## ESH&Q Building 120 Facility Risk Assessment

Area/Facility Description Title: SHSD FRA-01 Area/Facility # (if applicable): Building 120	Point Value → Parameter ↓	1	2	3	4	5
Area/Facility Description: Office building, one lab, and associated shed and trailer	Occupancy or Use (A)	<pre><once pre="" year<=""></once></pre>	<pre><once month<="" pre=""></once></pre>	≤once/week	≤once/shift	>once/shift
Name(s) of Risk Team Members: Fred Horn, Carol Ogeka, Arthur Piper, Gerard Shepherd, Chris Weilandics, Anna Bou	Severity (B)	First Aid Only	Medical Treatment	Lost Time	Partial Disability	Death or Permanent Disability
Approved by: Robert Selvey SHSD OSH POC Date: 04/10/06 Rev.#: 1	Likelihood (C)	Extremely Unlikely	Unlikely	Possible	Probable	Multiple
<b>Reason for Revision (if applicable):</b> Updated table format to inclumatch SHSD format for other FRAs.	Comments:					

		Without Controls			Control(s)	Risk with Controls in Place		in		Risk with Additional Controls in Place						
Physical Item or Activity	Hazard(s)										Control(s) Added to Reduce Risk					tion
		Occupancy A	Severity B	Likelihood C	Risk* AxBxC		Occupancy A	Severity B	Likelihood C	Risk* AxBxC		Occupancy A	Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction
Walking	Slips, trips, and falls	4	4	3	48	Lighting, building maintenance, new stair treads and handrails, Tier I inspections, general housekeeping	4	2	3	24						
Walking on ice/snow (outdoor hazards associated with winter)	Slips, trips, and falls (contusions, fractures, broken bones, back injuries)	4	4	4	64	Application of sand and salt on icy walking surfaces, drainage at water collection points, grounds maintenance, delayed opening of BNL, wearing appropriate footwear	4	3	4	48						

ESH&Q/SHSD FRA-01 page 1 of 3

## ESH&Q Building 120 Facility Risk Assessment

Indoor air quality	Allergies, asthma, headaches, pulmonary exposure, hazards associated with animal living beneath the building	4	2	3	24	Building maintenance, changing air filters from A/Cs and heaters as needed, grounds maintenance (removal of water that could lead to mold), recirculation quality (air exchange rate)	4	2	3	24			
General Fire Hazards	Fire Hazards	4	4	4	64	Fire extinguishers, fire alarms, water sprinklers, Tier I inspections, building maintenance, general housekeeping to reduce combustibles, SBMS fire safety subject area	4	2	2	16			
Working with electrical equipment	Electrocution, electrical shock	4	4	3	48	Tier I inspections, compliance with applicable OSHA regulations, general building maintenance, proper maintenance and inspections of equipment	4	2	2	16			
ечиртен	Fire	4	4	3	48	Tier I inspections, compliance with OSHA regulations, general building maintenance, proper maintenance and inspections of equipment	4	2	2	16			
Ergonomics (general office work)	Carpel tunnel syndrome, back/neck injuries, eye strain	4	2	4	32	Ergonomic reviews and evaluations, training such as back safety training, improved equipment, Tier I inspections	4	2	4	32			
Low Level Rad exposure associated with Building 356 and sealed sources from 120 laboratory	Exposure to low levels of radiation	4	1_	1_	4	Monitoring, training requirements for personnel entering building 356, posting as appropriate, appropriate storage and use of sealed sources	4	1	1	4			
Security	Security hazards associated with working alone and/or late at night	4	3	3	36	Adequate lighting, buddy system, working door locks, escort service	4	3	1	12			
Water Bottle Storage	Gastro-intestinal problems due to elevated bacterial levels	4	2	3	24	Proper storage of water bottles, monitoring of water quality, procedure for cleaning and handling water bottles	4	2	3	24			
Working with hot surfaces such as photocopy machine, stove and coffee-maker	Burns	4	4	3	48	Automatic timer device for coffee- maker, Tier I inspections, adherence to manufacturer's instructions of appliances	4	2	2	16			

ESH&Q/SHSD FRA-01 page 2 of 3

## ESH&Q Building 120 Facility Risk Assessment

Storage of calibration gases (such as methane, CO2, CO, hydrogen, and nitrogen) and small quantities of corrosives in 120 lab	tential 4	4	4	64	Appropriate PPE when handling substances such as face shield, safety glasses, and nitrile gloves, compliance with applicable SBMS procedures for storage and handling of chemicals and gases, Tier I inspections, training requirements, postings, signs, labels, and emergency placard outside door (green board)	4	2	2	16						
---	-----------	---	---	----	--	---	---	---	----	--	--	--	--	--	--

Further Description of Controls Added to Reduce Risk:											
*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater						
	Negligible	Acceptable	Moderate	Substantial	Intolerable						

ESH&Q/SHSD FRA-01 page 3 of 3